


In the spring of 2007, the County hired independent engineering firms to evaluate the county's corrections facilities. These evaluations are summarized in the following charts.

# Understanding the Issues



## Current Facility Evaluation

Security								
Security Perimeter	GOOD		POOR		MODERATE		PROBLEMATIC	GOOD
Security Systems	GOOD		PROBLEMATIC		POOR		PROBLEMATIC	GOOD
Functional Layout	MODERATE		POOR		GOOD		PROBLEMATIC	GOOD
Intended Use	GOOD		PROBLEMATIC		MODERATE		PROBLEMATIC	GOOD
Correctional Standards Issues	MODERATE		PROBLEMATIC		POOR		POOR	GOOD
Safety								
Safety of Staff	MODERATE		PROBLEMATIC		MODERATE		POOR	GOOD
Safety of Inmates	MODERATE		PROBLEMATIC		POOR		POOR	GOOD
Safety of Public Within Facility	GOOD		POOR		POOR		PROBLEMATIC	GOOD
Safety of Public Outside of Facility	GOOD		MODERATE		MODERATE		PROBLEMATIC	GOOD
Warm, Safe and Dry								
Age of Building	MODERATE		PROBLEMATIC		POOR		PROBLEMATIC	GOOD
ADA	GOOD		PROBLEMATIC		MODERATE		PROBLEMATIC	GOOD
Building Code Issues	POOR		PROBLEMATIC		MODERATE		PROBLEMATIC	GOOD
Structural Systems	MODERATE		MODERATE		MODERATE		PROBLEMATIC	GOOD
Mechanical Systems	GOOD		PROBLEMATIC		PROBLEMATIC		PROBLEMATIC	GOOD
Electrical Systems	GOOD		PROBLEMATIC		PROBLEMATIC		PROBLEMATIC	GOOD
	GOOD							
OVERALL EVALUATION:	MODERATE		PROBLEMATIC		POOR		PROBLEMATIC	GOOD



Hamilton Co.  
Justice Center



Queensgate  
Facility



Reading Road  
Facility



Turning Point  
Facility



New Facility

LEGEND	
CONDITION	
GOOD	GOOD
MODERATE	MODERATE
POOR	POOR
PROBLEMATIC	PROBLEMATIC


# Understanding the Issues




## Current Facility Evaluation – Hamilton Co. Justice Center

<b>Security</b>	
Security Perimeter	GOOD
Security Systems	GOOD
Functional Layout	MODERATE
Intended Use	GOOD
Correctional Standards Issues	MODERATE
<b>Safety</b>	
Safety of Staff	MODERATE
Safety of Inmates	MODERATE
Safety of Public Within Facility	GOOD
Safety of Public Outside of Facility	GOOD
<b>Warm, Safe and Dry</b>	
Age of Building	MODERATE
ADA	GOOD
Building Code Issues	POOR
Structural Systems	MODERATE
Mechanical Systems	GOOD
Electrical Systems	GOOD
<b>OVERALL EVALUATION:</b>	
	MODERATE

GOOD




MODERATE



POOR



PROBLEMATIC



Hamilton Co.  
Justice Center



Inadequate parking in Sallyport



Overview of HCJC


# Understanding the Issues



## Current Facility Evaluation – Queensgate Facility

<b>Security</b>	
Security Perimeter	PROBLEMATIC
Security Systems	PROBLEMATIC
Functional Layout	POOR
Intended Use	PROBLEMATIC
Correctional Standards Issues	PROBLEMATIC
<b>Safety</b>	
Safety of Staff	PROBLEMATIC
Safety of Inmates	PROBLEMATIC
Safety of Public Within Facility	POOR
Safety of Public Outside of Facility	MODERATE
<b>Warm, Safe and Dry</b>	
Age of Building	PROBLEMATIC
ADA	PROBLEMATIC
Building Code Issues	PROBLEMATIC
Structural Systems	MODERATE
Mechanical Systems	PROBLEMATIC
Electrical Systems	PROBLEMATIC
<b>OVERALL EVALUATION:</b>	
	PROBLEMATIC

GOOD



MODERATE



POOR



PROBLEMATIC



Queensgate  
Facility



Exposed electrical and telecommunications conduit in inmate areas.



Damage to spray-applied fireproofing - code-required fire resistance.



Deterioration of stone foundation walls



Non-compliant stairs create safety and security risks for staff and inmates


# Understanding the Issues



## Current Facility Evaluation – Reading Road Facility

<b>Security</b>	
Security Perimeter	MODERATE
Security Systems	POOR
Functional Layout	GOOD
Intended Use	MODERATE
Correctional Standards Issues	POOR
<b>Safety</b>	
Safety of Staff	MODERATE
Safety of Inmates	POOR
Safety of Public Within Facility	POOR
Safety of Public Outside of Facility	MODERATE
<b>Warm, Safe and Dry</b>	
Age of Building	POOR
ADA	MODERATE
Building Code Issues	MODERATE
Structural Systems	MODERATE
Mechanical Systems	PROBLEMATIC
Electrical Systems	PROBLEMATIC
<b>OVERALL EVALUATION:</b>	
	POOR

GOOD



MODERATE



POOR



PROBLEMATIC



R

Reading Road  
Facility



Windows do not meet detention standards



Deteriorating concrete roof deck



Exposed electrical and telecommunications in the exterior physical fitness area

# Understanding the Issues



## Current Facility Evaluation – Turning Point Facility

<b>Security</b>	
Security Perimeter	
Security Systems	
Functional Layout	
Intended Use	
Correctional Standards Issues	
<b>Safety</b>	
Safety of Staff	
Safety of Inmates	
Safety of Public Within Facility	
Safety of Public Outside of Facility	
<b>Warm, Safe and Dry</b>	
Age of Building	
ADA	
Building Code Issues	
Structural Systems	
Mechanical Systems	
Electrical Systems	
<b>OVERALL EVALUATION:</b>	



Egress component does not meet ADA or building code requirements




Windows do not meet detention standards.




Stairs do not meet building code requirements

GOOD



MODERATE



POOR



PROBLEMATIC



T

Turning Point  
Facility